

**Addendum to
Disclosure Report
St. Paul Truth-In-Sale of Housing**

Property Address: 10516 Blaisdell Cir

<u>Item #</u>	<u>Comments</u>	<u>Item #</u>	<u>Comments</u>
77. B	Damaged slab and exposed block (Cores are visible at the top through the garage floor) at East side.		
77. C	Slab cracks were noted in the garage floor.		
80. H	Melted plastic on garage door opener. Improperly wired light @ opener: exposed electric contacts. Missing electric cover-plate(s).		
89. B	Shed has a damaged door, damaged trim/fascia, improperly installed siding (missing flashing detail) siding is less than 6" from grade. Poor detail at roof edge.		
89. C	Shed is locked and interior was not accessed or evaluated.		

SIGNATURE: _____ PHONE: _____

EVALUATOR: _____ DATE: 03/23/2010 Page 1 of 1